

## **General Attendance Requirements**

- 1. 2 x 240 volt / 13amp. Alternatively, 2 x 110 volt / 32 amp electric power to the workface.
- 2. Use of welfare facilities.
- 3. All dust sensitive work areas and equipment to be screened off and covered before our commencement.
- 4. Use of a waste skip to deposit site debris.
- 5. Work areas to be free of other trades and their equipment during our installation and curing programmes.
- 6. Extension of daily and weekend working hours to be accommodated when necessary.
- 7. Areas assumed to be dry, clear and clean prior to our commencement.
- 8. Use of forklift truck for off-loading deliveries of materials and warm, dry storage.
- 9. Deliveries of materials and plant prior to our arrival to be accepted by you / your client's representative and all documentation retained for our records and handed over on our arrival.
- 10. Minimum ambient temperature to be maintained at 10°C during our installation and curing programmes.
- 11. All moveable plant and machinery to be moved prior to our arrival.
- 12. General standard of lighting to be maintained to approx. 300 lux.
- 13. Weekend working hours deemed to be 6pm Friday to 6pm Sunday unless otherwise stated.

**N.B.** The application of the floor finish specified overleaf will not enhance or otherwise affect the general falls / levels in the concrete base. As the finish is laid by hand minor differences in thickness may occur and depressions may









Lasercroft Ltd 9 Hedon Road Kingston Upon Hull East Yorkshire HU9 1LH Telephone 01482 229 119 Email info@lasercroft.com www.lasercroft.com